

REPORT OF SHIP SURVEYS AND REPAIRS

Received London
-2. OCT. 1962

Ship's Name SS/MS "STRANTON" Gross tons 145
a rpt. 9? Yes Port W. HARTLEPOOL. Rpt. No. 20293
No. of visits 1 First date and Last date 21-9-62.
Cert. issued hereewith? Yes Damage rpt. issued & copy herewith? No Last rpt. (H.Q. only) 20229 SPL
Date of letting rpt. 21-9-62. Surveyed at, if different from Port above -
Laid afloat or in D.D. Drydock Last date of examination in D.D. 21-9-62
Load Line been held? Yes Freeboard Marks verified 21-9-62

State which additional Rpt. 8 is attached: (Carr); (PS); (DR); (EQ); (Rig)
Docking survey fees £3 Damage fee - Expenses -
S.A. fee -

Surveyed the above ship in accordance with the Rules for Drydocking.

Now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

Recommend that this ship remain as classed with/without fresh record of dry docking 9,62.


re conditions of class are recommended to
ained, imposed, amended or deleted, particulars
be stated above and on the interim certificate.)

of Committee THURSDAY 25 OCT 1962

te

DS 9.62

W. Robinson
Surveyor to Lloyd's Register of Shipping



011330-011340-0183-2

© 2021

Lloyd's Register
Foundation

94
ALSO FOR

SPL FOR

TRO

SRL ✓

POSTING ✓

HEADER ✓

CERT

P.S.) DRY CARGO SHIP

Ship's Name **"STRANTON"** S.S. (**'A'**) Due **11, 63.**
 Port **W. HARTLEPOOL.** Rpt. No. **20293**

Examined & condition	Examined & condition
clock from 21-9-62	* Air & sounding pipes above deck - good.
to	Doublers under " " Not exd.
shell plating Good	Steering arrangements (main) Good
sternframe Good	" " (aux) Good
Rudder Good	Windlass Good
derlifted? No	Masts & rigging Good
etc. in way of openings None	Hand pumps & suction Not exd.
side scuttles Good	W.T. doors None
deadlights Good	Bulwarks, freeing ports, etc. Good
d. scuppers Good	
discharges	
F.P. spaces	Summer freeboard as verified 1'-9½" <i>Not in R.B.</i>
hain locker	
A.P. spaces	
ngine space	
Boiler space	
er E. & B.	
Coal bunker	
nnel & well	
ent, asphalt.	
n btm. shell	
weather decks Good	
* Casings Good	
Deckhouses } Good	
erstructures }	
* Skylights Good	
panionways Good	
Hatchways Good	
Ventilators Good	
Other items: -	

EQUIPMENT:

Equipment letter	(c) ✓
Fee ltr., if diff. from eqpt. ltr.	-
Anchors: No. on board	2
State if ranged	No
Length on board	not ranged.
Mean dias. range from	- to -
Rule length	- Dia. -
Mooring ropes	Sufficient


PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC. The reason for repairs must be stated on account of damage, the alleged cause of which must be given, should be detailed separately from wear repairs and, besides being detailed above, should be noted in the following summary. State what action taken regarding items which are subjects of class or in SRL Appendix, whether outstanding or new. Any alterations existing particulars in the Register Book should also be reported above.

SUMMARY OF DAMAGE REPAIRS	SHELL PLATES	FRAMES	DECK PLATES	BEAMS	OTHER ITEMS
Renewed					
Removed and faired or replaced					
Faired or repaired in place					

Items to include their closing appliances
 as a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"

(MADE AND PRINTED IN ENGLAND)

HOLDS & 'TWEEN DECKS:		Examined & condition	TANKS:	Examined & condition	Tested & condition
No. 1	Hold	Not examined.	F.P. tank		
"	'Tween decks		A.P. tank		
			D.B. tanks & c/dams		
No. 2	Hold				
"	'Tween decks				
No. 3	Hold		O.F. bunkers		
"	'Tween decks				
No. 4	Hold		Settling tanks		
"	'Tween decks				
No. 5	Hold		Deep tanks		
"	'Tween decks		Side tanks		
No. 6	Hold		Wing tanks		
"	'Tween decks				
			Other tanks:		
	Cargo battens				
	Ceiling, etc.				



surveyed
on 21st
drydock

and the
Shipping
recommen
of dryd



© 2021

Lloyd's Register
Foundation

This Certificate
"While the
understood the
inaccuracy in
or for any error
of the Society
Cert. B 80m