

total capacity tons. FPT tons, API tons, M1
N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

CHARACTER.
* for Special Survey
Date of last Survey and of
Periodical Surveys.

Year
Assigned
new
expired

Machinery and Boiler
surveys
(Including date of N.B., if
any)

2m,8,36.

- 5 JAN 1937

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

"HORDEN"

Rpt. Nwc.

No. 94476

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

The class is subject to indented plating etc. on port side being repaired at the first convenient opportunity.

Action has been deferred in this case for examination in dry dock after grounding.

The Newcastle Surveyors now report the vessel placed on a pontoon and the requirements of the 2nd S.S.No.2, due 11,36, partly complied with.

On account of damage through grounding repairs have been effected to shell plating, framing, bilge keels, steering gear etc.

Repairs are required to stringers in aft peak tank and some scaling and coating is required.

The indented plating, as above, has not been dealt with.

It is submitted action be deferred.

Delete from S.R.L. 'Dry docking (grounding)'

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book



© 2020

Lloyd's Register
Foundation

Special Damage or Repair Fee (if any) £ 10 : 10 : 0

Travelling Expenses (if chargeable) £

Surveyor's Fee (if any) £ 1 : 1 : 0

Received by me

21.11.37

02.12.37

Surveyor to Lloyd's Register of Shipping.