

31955

22nd February, 1957.

971,2004,41 - As recommended.

"JA" Before your Report No. 31955 receives consideration, point out that your Rpt. 9 contains no reference to the examination, and, in the circumstances, I shall be glad whether the requirements of Circular No. 1959 have been with.

In regard to the examination of the screwshaft, a limit of months for re-examination is considered a "short" limit, such the record of Screwshaft examination 12,58 has been

I shall also be glad to learn whether the tapered part of the shaft can be satisfactorily examined without completely the shaft. Your recommendations should be worded gly.

In the circumstances, it is considered an amended Rpt. 9 should be issued, and I shall be glad if you will forward this document to the office as soon as possible.



© 2020

Lloyd's Register Foundation

011360-011367-0235

011357-0237