

No. of Aux./Donkey Boilers

W.P.

\* 100 AI.

Surveyed Afloat or in Dry Dock

BOTH.

Nature of Survey DeKq; TSCL; GENERAL EXAM.

shelter deck with freeboard.

Dec

7 55

"MONTE SAJA"

Ant.31955.

BEFORE THIS CASE receives consideration, submitted the Surveyors be informed there is no mention on their Rpt.9 as to whether a General Examination of the machinery has been carried out. They should, therefore, state whether all the requirements of Circular 1959 have been complied with, bearing in mind the fact that they were fully advised in our letter of 12.12.56.

With regard to the screwshaft, a limit of 12 months for re-examination is considered to be a "short" limit, with the result that a fresh record of 12/56 will be withheld. Further, they should clarify whether the tapered part of screwshaft can be satisfactorily examined without completely drawing the shaft, and word their recommendations accordingly.

In all the circumstances, it is considered an amended report should be furnished as soon as possible.

18.2.57.

© 2020

Lloyd's Register  
Foundation

01360-01367-0245

16 SCAVENGE BLOWERS

17 SUPERCHARGERS

MAIN TURBINES

placed in good  
ced before the  
lly under "de  
e machinery is  
bers should be

nds

17-12-56

YE