

Chief Surveyors

3. 11. 36

Received from Chief Surveyors

NAME

L. S. Vizagapatam

Report

Cal

No. 9798

For the ~~CHIEF SHIP SURVEYOR~~ and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

~~No.~~ Boiler SURVEY PARTLY HELD.

11/36

When proposed to be completed


Survey held, &c.,

To complete the Boiler Survey due 11,36, partly held 8,36, the safety valves require to be adjusted under steam.

In reply to enquiry the Calcutta Surveyors state that the safety valves have been adjusted by the Mechanical Superintendent of the Port of Vizagapatam.

It is submitted this inspection be accepted and a record of B.S. 8,36 assigned.

5.11.36



© 2021

Lloyd's Register
Foundation

011368-011377-0686