


Motorship "PACIFIC BUILDER"

Mr. Hsu telephoned and stated that he has now received further information from Tokyo, and it appears that this ship has experienced machinery trouble during the voyage from Singapore to Formosa.

In these circumstances the Owners have decided to send her from Formosa to Hong Kong where the machinery can be fully opened out for survey, and the Owners will then decide whether to repair the ship or sell her for scrap.

hm

9th September, 1959.



© 2021

Lloyd's Register

011368-01877-0165
Foundation