

25 OCT 1963

Ship's Name SS/MS ELKENCI Gross tons 7046
Is there a rpt. 9? NO Port Istanbul Rpt. No. 5421
No. of visits one First date and Last date 22.10.63
Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? No Last rpt. (H.Q. only) HQS 710
Date of completing rpt. 22.10.63 Surveyed at, if different from Port above --
Surveyed afloat and/or in D.D. afloat Last date of examination in D.D. --
Has a Load Line Survey been held? No Freeboard Marks verified --
State which additional Rpt. 8 is attached: (~~Cont.~~); (PS); (DR); (~~EQ~~); (~~Rig~~)
Survey fees TL. 300.00. Damage fee 52. Expenses
S.A. fee

I have surveyed the above ship in accordance with the Rules for

Annual Hull survey

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

Minor repairs only:

Door clips freed and 2 side light glasses renewed

Condition of class indented shell plating in way of No. 2 hold
aft and port side to be specially examined
and dealt with as necessary at the next
dry docking.

Shell plates examined and found satisfactory meantime.
It is submitted that the condition of class be continued.

Endorsement of class
Shell plates B4 and C4 port side aft slightly indented
these plates were under water and could not be examined at
this time.

It is submitted that the endorsement of class be continued.

I recommend that this ship remain as classed with/without fresh record of dry docking and
subject to indented shell plating in way of No. 2 hold aft end
port side to be specially examined and dealt with as necessary
at the next dry docking

(Where conditions of class are recommended to
be retained, imposed, amended or deleted, particulars
must be stated above and on the interim certificate.)

Date of Committee

Minute

G. J. Boulter

Surveyor to Lloyd's Register of Shipping

FRIDAY 22 NOV 1963

As now subject



ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

Lloyd's Register
Foundation

Rpt. 8 (P.S.) DRY CARGO SHIP

Ship's Name SS/MS ELKENCI

S.S. () Due

Istanbul

Port

Rpt. No.

542I

| | <u>Examined & condition</u> | | <u>Examined & condition</u> |
|--|---------------------------------|------------------------------------|---------------------------------|
| In dry dock from | - | * Air & sounding pipes | good |
| " " " to | - | Doublers under " " | not examined |
| Shell plating | good | Steering arrangements (main) | good |
| Sternframe | not examined | " " (aux) | good |
| Rudder | " | Windlass | good |
| Was rudder lifted? | No | Masts & rigging | good |
| Plating, etc. in way of shell openings | None | Hand pumps & suction | good |
| Side scuttles & deadlights | good | W.T. doors | good |
| Overbd. scuppers & discharges | good | Bulwarks, freeing ports, etc. | good |
| F.P. spaces | good | Summer freeboard as verified | 5578 ✓ 11'-1" |
| Chain locker | not examined | | |
| A.P. spaces | good | | |
| Engine space | good | | |
| Boiler space | good | | |
| Under E. & B. | not examined | <u>EQUIPMENT:</u> | |
| Coal bunker | none | Equipment letter | a + 2' sea |
| Tunnel & well | not examined | Fee ltr., if diff. from eqpt. ltr. | |
| Cement, asphalt, etc., on btm. shell | " | Anchors: No. on board | 3 |
| Weather decks | good | State if ranged | No |
| * Casings | good | Length on board | |
| * Deckhouses | good | Mean dias. range from | to |
| * Superstructures | good | Rule length | Dia. |
| * Skylights | good | Mooring ropes | sufficient |
| * Companionways | good | | |
| * Hatchways | good | | |
| * Ventilators | good | | |
| Other items: | | | |

* These items to include their closing appliances

Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"



© 2021

J. Boulter
Surveyor to Lloyd's Register of Shipping

Foundation

| HOLDS & 'TWEEN DECKS: | | Examined & condition | TANKS: | Examined & condition | Tested & condition |
|-----------------------|---------------|-------------------------|---------------------|-------------------------|-----------------------|
| No. 1 | Hold | Not examined | F.P. tank | | |
| " | 'Tween decks | | A.P. tank | | |
| | | | D.B. tanks & c/dams | | |
| No. 2 | Hold | good | | | |
| " | 'Tween decks | good | | | |
| No. 3 | Hold | good | O.F. bunkers | | |
| " | 'Tween decks | good | | | |
| | | | Settling tanks | | |
| No. 4 | Hold | not examined | | | |
| " | 'Tween decks | | Deep tanks | | |
| No. 5 | Hold | not examined | | | |
| " | 'Tween decks | | Side tanks | | |
| No. 6 | Hold | --- | Wing tanks | | |
| " | 'Tween decks | | Other tanks: | | |
| | Cargo battens | - | | | |
| | Ceiling, etc. | good | | | |



© 2021

Lloyd's Register
Foundation