

Ship's Name	SS/MS	SAM FLORO	Gross tons
Is there a rpt. 8?	Port	Bilbao	Rpt. No. 13534
No. of visits	First date	Last date	
Interim Cert. issued & copy herewith?	Damage rpt. issued & copy herewith?	Last rpt. (H.Q. only)	
Date of completing rpt.	Surveyed at, if different from Port above		
Is a rpt. 9A attached?	Yes	MN	Nature of survey Docking and C.S.
Survey fees	Damage fee	Expenses	
S.A. fee			

DOCKING			
Propeller	Good	Sea connections	Good
Fastenings	Good	Oil gland	2 mm
Has screw/tube shaft been drawn?	No	Wear down of stern bush	-
Has shaft been changed?	-	Date of examn.	-
Has shaft now examined/fitted a continuous liner?		Has shaft now fitted been previously used?	-
Approved oil gland?		-	

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, DONKEY OR PRESS	(State if oil fired—OF or exhaust gas—EG)	MAIN
Air heaters		
Superheaters		
Safety valves		
Mountings, doors and fastenings		
Safety valves adjusted to { Sat Spt		
Boiler securing arrangements		
Main economisers	Exhaust gas heated economisers	
Steam heated steam generators	Steam generator safety valves adjusted to	
Forced circulating pumps	Funnel	
Have saturated steam pipes in cylindrical boiler smoke boxes been examined as required by the Rules?	Were oil burning system & remote controls examined in accordance with rules?	

I recommend that the machinery of this ship remain as classed with/without fresh record of

See Rpt. 9 A

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

MONDAY 30 SEP 1963

See Rpt 9 A

Surveyor to Lloyd's Register of Shipping

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

Lloyd's Register Foundation