

# LOYD'S REGISTER OF SHIPPING

OFICINA PRINCIPAL: FENCHURCH STREET, 71. LONDRES, E. C. 3.

alle Gran Vía, 83, 1.º izqda.

Apartado de Correos N.º 286, Bilbao

Telegramas: Register, Bilbao

30th December, 1958

Teléfono 16995

Dear Sir,

M.V. "SAN FLORO"

With reference to your Classing letter the 23rd inst. regarding Bilbao Report N° 12458 the above vessel, we have to confirm that the rudder hatch has been removed at this time and the General Service Pump examined at this time is in fact, the Ballast pump.

Due note has been taken regarding the operation of Main Engine friction damper, and arrangements will be made for this item to be examined at the first opportunity.

Yours faithfully,  
Secretary,

T. J. Morris

© 2021  
Lloyd's Register  
Foundation

011421-011426-0066



SR ER

CLASSIFICATION

H

RM

R. 2/1

12/1/59

12-12 Dam

12/15

Noted  
J. 12/15/59



© 2021

Lloyd's Register  
Foundation