

4E

Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

NAME SAN FLOROREPORT BILBAONo. 1057

C.S. advanced 2 cycle completed.
 Dredging Tail Shaft seen
 S.R.L. offender. The item now dealt with

It is submitted that this
 vessel is eligible for **THE**

RECORD. TS (CL) 10.58 & C.S. 11.58

Offender delist item.

9/11
 18/12/58

© 2021

The main engine Section Dwyer does not appear
 to have been examined during the last four years and
 the owners should arrange for this item to be dealt with
 their earliest convenience. It is concluded that the
 engine part referred to as examined was in fact the Bullard Pump
 as clear for Dwyer.

Lloyd's Register
 Foundation