

Messrs. Corcho Hijos S.A.

Yard No. 65.

2,500,1154 Blk.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

SHIP'S NAME m.s. "SAN FLORO"

REPORT Bbo.

No. 11970

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

L. 199'-6"

B. 32'-0"

D. 18'-6½"

The scantlings and arrangements, as reported, conform with the Society's Revised Rules and Regulations, and are in accordance with or equivalent to those shown on the approved plans.

IT IS THEREFORE SUBMITTED the ship is eligible to be classed:-

\*100A1

4,56 Santander

1 dk & S dk; O.S.D; pt E.W.

DB pt W.B. 174t pt O.F; DTa O.F; FPT 56t; APT F.W.

Coll BH to S dk; 4 to 2nd dk; LACP.

F 20'


Mchy Aft

O.L. 223'-2"

Extreme breadth: 32'-2"

Rise of floor: 4"

" 8 "



R.S.P.

14.8.56.

modified to two deck ship

Bilbao 11/58

© 2021

Lloyd's Register Foundation