

46324

LLOYD'S REGISTER OF SHIPPING

25 MAY 1959

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name M.S. "SAN FLORO" Official No. _____

Port of Registry Santander

This ship has been under survey at Bilbao Rpt 12592

on 14th - 30th April, 1959 and the following alterations to the conditions of

assignment of loadlines have now been effected/~~found~~—

FORECASTLE DECK

1 - 250 m/m dia; Cowl ventilator (coaming 8 m/m x 915 m/m in height) to forecastle tween deck store, now removed. Opening in deck permanently closed with steel plate, electric welded to deck.

John H. White

T.M.H.

A copy of this Report has been placed on board.



© 2021

Lloyd's Register Foundation

*Noted
J.M.B.
26/5/59*