

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
 { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

16th October, 1964.

Yr.Ref. 042-01

C.
AH/DET

Dear Sirs,

M.S. "CINDERELLA"

I acknowledge receipt of your letter of the 13th instant, the contents of which have been noted.

In reply to the third paragraph of your letter, I have to inform you that due to stated heavy weather damage the screwshaft was drawn in January 1958 and the liner found to be fractured. No further details were given by the Surveyor.

I have to add that the Society has no record of any liner replacement relative to the original shaft.

Yours faithfully,

Deputy Clerk to the
Classification Committee

Messrs. S. A. Enchimar,
30, Boulevard du Regent,
BRUSSELS,
Belgium.



© 2021

Lloyd's Register
Foundation

011433-011440-0112