

ENCHIMAR

SOCIÉTÉ ANONYME A BRUXELLES (BELGIQUE)

BUREAUX : 30, BOULEVARD DU RÉGENT, BRUXELLES 1

C. CH. P. BRUXELLES NO 15460
REG. DU COM. BRUX. NO 269.619
TÉLÉGR. ENCHIMAR - BRUXELLES
TÉLÉPHONES : 13 39 67 (3 LIGNES)
TÉLEX - 2 - 21635 ENCHIMAR - BRU

C

BRUXELLES, le October 13th, 1964

Votre référence : AH/RW

Notre référence : 042-01

Factures en TRIPLE exemplaire s. v. p.
Invoices in TRIPLICATE please

LLOYD'S REGISTER of SHIPPING
71, Fenchurch Street
LONDON E.C.3

England.

Dear Sirs,

m/v CINDERELLA - Screw shafts.


We beg to acknowledge with thanks receipt of your letter of 8th instant, contents of which have had our best attention.

From the history data supplied by your kind investigation, we noted to our surprise that the shaft marked C 184 BC F 153 RS 12.7.63 was fitted with a new bronze liner in January 1958, after only 4 years and 4 months service, compared with the other shaft which has been in service for nearly 27 years with its original liner.

We wonder whether you could trace up and try to elucidate for what reason a new bronze liner had to be fitted in 1958. This information might help us considerably from a technical point of view.

Thanking you in anticipation for your kind cooperation, we beg to remain, Dear Sirs,

Yours faithfully,
S.A. ENCHIMAR
Le Directeur,



ROT
29.9.



© 2021

JTH/AW.

Lloyd's Register
Foundation

011433-011440-0113

M

Submitted Writers be
advised in reply to their form of
their letter of 13.10.64, that due to
stated heavy weather damage, the
snowshaft was damaged & the lines
fractured. As further details were given by
the Surveyor. The Writers should also be advised that the Society
has ~~not~~ record of any line's replacement relative to the
original shaft.

G.A. 16.10.64 *AK*



© 2021

Lloyd's Register
Foundation