

21 SEP 1964

Ship's name "CINDERELLA" Port LA No. 22

Last survey date 16.7.64.

GB Class is subject to fractured shell plates Nos.1 & 2 in
3rd below sheer in way of A.P.tank (p.s) (temporarily
repaired 6,64) being specially examined and dealt with
as necessary at the next drydocking.

S.R.L. Appendix (~~as before~~ none)

Surveys due SPECIAL SURVEY (C) due 1,65. Proposal to postpone
the S.S. approved 10.4.64 subject to the requirements of a G.E.
in dry dock by 11,64, period of postponement being dependent
upon condition of ship as found and reported upon at G.E.

Nature of present survey (afloat ~~and in drydock~~)

Deferred repairs due to contact damage.

Is interim certificate in order Yes/No/None

Items outstanding if any for SS

ALL ITEMS.

SS proposed to be completed by

Recommendation SUBJECT as above.

As Now. Subject.

INSERT IN S.R.L. APPENDIX.

Common landing of shell plates
G.19 and H.18 (s.s.f) slightly indented.

21.9.64



© 2021

Lloyd's Register
Foundation