



... through wa... tight b... heads... are they fitted with watertight doors. No... Are the door frames...

... Where are the doors worked from... Insulation and Appliances examined in the following refrigerated spaces:—

# COPY LLOYD'S REGISTER OF SHIPPING

(UNITED WITH THE BRITISH CORPORATION REGISTER)

... provision for defrosting...  
 No. 3 Hold Upper Tween Deck.  
 Starb'd forward cargo chamber  
 Starb'd after " " " "  
 Port forward " " " "  
 Port centre " " " "  
 Port after " " " "



... 3-5-55 and Insulation 3-5-55  
 "Haguro Maru"  
**LOADING CERTIFICATE FOR VESSELS HOLDING LLOYD'S REFRIGERATING MACHINERY CERTIFICATE.**

The temperature in the cargo chambers were noted to be as follows:—  
 M.V. "HODAKASAN MARU" of Tokyo.

**This is to Certify** that the Loading Port Survey  
 Starboard forward cargo chamber  
 Starboard after cargo chamber  
 Port forward cargo chamber  
 Port after cargo chamber  
 in Lloyd's Register Book here issued at the Port of Kobe  
 dated 20.5.55  
 states that a later record of LLOYD'S R.M.C. 755 has been recommended.

The insulation and Appliances of the chambers specified overleaf have been examined by me and I found the insulation undamaged and clean, the dunnage battens, where these are required, in good order, and the refrigerating machinery, when tested under working conditions also in good and satisfactory order.

I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me have been completed to my satisfaction.  
 Before loading was commenced, the temperature of the cargo chambers was reduced as shown overleaf, and in my opinion the vessel is fit to carry refrigerated cargo in the chambers now examined during the contemplated voyage to U.S.A.

ENTERED IN REGISTER BOOK		INSULATED CARGO CHAMBERS	
Makers	No.	No.	Capacity
<i>J. J. J.</i>	5	14,000	

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
 "While the Committee of the Society are their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any loss or damage in any report or certificate issued by the Society or its Surveyors or in any entry in the Register Book or other publication of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors or other Officers or Agents of the Society."

**FOR LONDON**

Lloyd's RMC 755