

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex  
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

4th November, 1964.

C  
DNS/CB

Dear Sirs,

## CLASSING LETTER

13367"HODAKASAN MARU". As recommended.

It is noted that the screwshaft was found to be in accordance with the Rules for four-yearly surveys and you may, therefore, inform the Owners that it will be in order for future Screwshaft Surveys to be held at four yearly intervals, the next survey becoming due in September, 1968.


You should also inform the Owners that if at any docking intermediate between Screwshaft Surveys the wear down of the stern bush is, in the opinion of the Society's Surveyor, excessive, the shaft will require to be drawn and the bush relined.

It should be added that no period in excess of four years will be allowed between Screwshaft Surveys beyond what is reasonable to enable the ship to reach a port where the survey can be held.

Yours faithfully,

pro Clerk to the  
Classification Committee.

The Surveyors,  
KOBE.



© 2021  
Lloyd's Register  
Foundation

011433-011440-0281