

Copy of supplement to Vancouver letter of 11th
January, 1944, with First Entry Report on "FORT YUKON".

The following First Entry Hull Reports from Vancouver, B.C.
should be modified so that under shell plating aft, on page 2,
the bottom plating (four strakes) and bilge plating (one strake)
read, in each case, .50" instead of .44".

<u>Shipbuilders.</u>	<u>Hull No.</u>	<u>Ship's Name</u>	<u>Rpt. No.</u>
Burrard Dry Dock Co. Ltd.	180	"Fort Columbia"	5942
North Vancouver, B.C.	182	"Fort Bellingham"	5954
	184	"Strathcona Park"	5953
	186	"Fort St. Nicolas"	5990
	188	"Fort Sakisdac"	6006
	190	"Fort Machault"	6023
	192	"Beaton Park"	6046
Burrard (Vancouver) Dry	181	"Fort Yukon"	5950
Dock Co. Ltd.	183	"Wascana Park"	5956
Vancouver, B.C.	185	"Fort Wascac"	5969
	187	"Fort Frudhomme"	6002
	189	"Fort Venango"	6018
	191	"Fort Orleans"	6035
	193	" <u>Fort St. Croix</u> "	6062
North Van Ship Repairs Ltd.	127	"Fort Hall"	5952
North Vancouver, B.C.	128	"Fort Clatsop"	5955
	129	"Fort Colville"	5970
	130	"Fort Panauere"	6001
	131	"Fort Marin"	6015
	132	"Fort Salcesh"	6025
	133	"Dundurn Park"	6045



© 2021

Lloyd's Register
Foundation

011444-011460-0308

© 2021
Lloyd's Register
Foundation

no alt number

1.c.d

مر

Total	Gross	Regist	RE	Length	Bread	Depth
FRA	SIDD	Fr	Dian	Stat	Are	Pd
Fr	Fr	an	an	an	an	an
M						