

COPY.

2-DEC 1947

Lloyd's Register of Shipping



Port QUEBEC, P.Q.

27th October, 1947

This is to Certify that I have

Surveyed the ^{Part}Boiler and ^{Part}Machinery of the Steel Single Screw Steamer "OAKMOUNT", 2883 Tons Gross, Register of Montreal on the 24th July, 1947 & subsequent dates whilst in the Champlain dry dock, Lauzon and afloat at Coal Wharf, Quebec for damage stated to have been caused through vessel grounding in Miquero Bay on the 23rd June, 1947 on a voyage from Miquero, Cuba, to St. John, N.B; and that I have transmitted ~~will~~ to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I ~~will~~ **Recommended** that the record of ~~L.M.C.~~ L.M.C. (with date)

be made in the Register Book in the case of this vessel when the survey has been completed.

Fitted for oil fuel 10,47 F.P. above 150°F. now.

Parts now examined:—

Screwshaft, propeller & fastenings, stern tube, bush & fastenings also sea connections, gratings & their fastenings.
Main Engine:— H.P. & I.P. cylinders, covers, piston, rings and rods.
H.P. & I.P. valve chests, covers, valves and rods.
H.P., I.P. & L.P. top and bottom ends.
All main bearings and thrust.
Crankshaft, thrust and intermediate shafting.
Link driven air and bilge pumps.
Holding down bolts.
Aux. Machinery: Bilge, Ballast, circulating, feed and C.S. pumps.
Main and auxiliary condensers.
Windlass engine, Feed heaters.
Oil fuel units, heaters, valves, strainers, piping also extended spindles.
Transfer pump.

D. L. L. L.
Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.