

COPY

LLOYD'S REGISTER OF SHIPPING



Port Havana, Cuba

Date 14th January, 1964

This is to Certify that I have

surveyed the S/S "OAK HILL"

7139 Gross tons of London

while afloat at this port on the 4th January, 1964, and subsequent dates for the purpose of examining and reporting the damage on main deck port side stringer plating abreast of No. 3 hatch stated to have been sustained due to heavy weather while in voyage from Leningrad to Havana

and that I am transmitting to the Committee of Lloyd's Register of Shipping, London, a report, stating that all repairs recommended by me have been completed to my satisfaction, also that I am recommending that she be remained as classed without record of Survey subject to main deck, port side stringer plating abreast of No. 3 hatch to be specially examined at next dry docking and dealt with as then found necessary.

Ernesto del Moral
Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

AS Annual Survey
BS Biennial Survey
DS Docking Survey
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey
SS(Dr) Hull Special Survey (Drilling)
SS(M) Hull Special Survey (Modified)
CSH Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B 80m.4,62 (MADE AND PRINTED IN ENGLAND.)

011485-011492-0016