

SHIP'S NAME

"OAK HILL"

REPORT Ply.

No. 8666

GB

Standing Conditions of Class:

Subject to wavy bottom plating being specially examined next drydocking.

Improvement of Class (B) (~~As before~~ or None)

Surveys due: SPECIAL SURVEY (C) due 5,58.

Nature of Present Survey: (~~Afloat and in dry dock~~)Commencement of Special Survey:
Recommendation for repairs.Special Features: Ship ~~is~~ now laid up in the River Dart.Interim Certificate in order (Yes-~~No~~-None)Surveys Outstanding: (~~If any for S.S. or A.S.~~)FOR PORTION OF SURVEY HELD:- See this report.

to be completed by:

Recommendation:

And notation of "5,58."

SUBJECT as above, and to recommended repairs being carried out by the Special Survey but further ACTION ~~be~~ DEFERRED for completion of the Special Survey.

SUBJECT

IN S.R.L. APPENDIX

Bottom stiffening fitted - Nwc. 5,50, with minor corrugations left unfaired).

OFFICE NOTE

Bottom stiffening fitted - Nwc. 5,50 with minor corrugations left unfaired.

S.S. PART HELD.



© 2021

Lloyd's Register
Foundation