

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

2, "Danby Lodge", Lincombe Drive, Torquay

Telephone & Telegrams: Torquay 4193

RECEIVED

28th February, 1959.

3 MAR 1959

Ans'd.....

Dear Sir,

Steamer "OAK HILL "


I am in receipt of your letter of the 27th instant, regarding the above vessel, which is at present laid-up in the River Dart.

On the back of my report under particulars of repairs etc., I very clearly stated, "it is not known whether these repairs have been effected." I very much doubt if anything has been done to any of the repairs since there is no crew on this vessel.

I have had no request from the Owners Superintendent to extend the life of the condenser doors, in fact he stated they were going to renew them and therefore they are included amongst the items to be dealt with for completion of the Special survey.

My report is returned herewith, should however, you require the wording to be amended in any way please return it to me and I will do so.

Yours faithfully,



The Secretary,
LONDON.



© 2021

Lloyd's Register
Foundation

011485-011492-0044

ER CLASSIFICATION

H 114

22/10/50.

R. A.

© 2021

Lloyd's Register
Foundation