

COPY

# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

71, Fenchurch Street, London, E.C.3

Telegrams : Committee, Fen, London

Telephone : ROYal 3551 (6 Lines)

25th May, 1956.

(S)

Dear Sirs,

Steamer "OAK HILL"

A report of survey has been received from the Society's Surveyors at Shimonoseki, from which it is noted that on account of damage stated to have been caused by heavy weather repairs have been carried out.

It was recommended, however, that 15 fathoms of chain cable be repaired and re-tested or renewed at the earliest opportunity and that the starboard chain cable be specially examined before the end of next month.

The Surveyors also reported that the safety valve chest of the starboard boiler was found cracked. Temporary repairs were carried out, and it is recommended that this item be examined before the end of next month and renewed before the end of September next.

The class has been continued subject to the above matters receiving attention as indicated, and I shall be obliged if you will kindly let me know what arrangements you propose making for the case to receive the necessary attention.

Yours faithfully,

Deputy Clerk to the  
Classification Committee

The Counties Ship Management Co. Ltd.,  
9, St. Helen's Place,  
LONDON, E.C.3.

Lloyd's Register  
Foundation

011485-011492-0055