

COPY

Ship's name <sup>83</sup> "CARDAMILITIS"

Port Chittagong

No. 661.

Class is subject to Nom.

Last survey date 21/11/64

MRB (due 2/12/64) not commenced.

Port boiler on bottom casing found distorted & leaking - the surveyor recommends that the Port boiler side and back lower casing be repaired by 2/15 (3mo).

It is submitted that the vessel **WILL BE** eligible for the record when the survey has been completed.

of starboard boiler and adjustment of the SVs, subject to recommendations.



© 2021

Lloyd's Register  
Foundation