


8  
Turnbull

Tanker "BEN HENSHAW"  
Classed B.S.


A Representative of the Owners, the National Benzole Company, has telephoned to say that the electric generator which supplies current to the electrically driven windlass is under repair ashore and may require fourteen days to complete. He states that the windlass is provided with arrangements for working by hand, and would like to know if the ship could continue to trade in the meantime using hand-operated windlass.

Submitted the Owners' Representative be advised that, provided arrangements are provided for the hand working of the windlass and found satisfactory by the Surveyors, the vessel could be allowed to proceed.

  
7th June, 1949.

Owners to be advised by phone

Owners will advise if & where this examination of the hand operated windlass will take place



© 2021

011524-011535-0035  
Lloyd's Register  
Foundation