

BRITISH CORPORATION.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

30 JUN 1949

GB

VESSEL'S NAME "BASKERVILLE" REPORT Mch. No. 13667

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

This vessel is classed BS\*

For outstanding repairs see attached list.

The MANCHESTER Surveyors report, the vessel placed in dry dock, bottom coated, and repairs effected to all outstanding items, as above, with exception of shell plates B.7 & C.7 (p & s) and slightly indented No.2. tank top in way.

The Surveyors however recommend repairs to these items need not be made a condition of class.

IT IS SUBMITTED these items be considered as blemishes.

IT IS FURTHER SUBMITTED the vessel is eligible to remain as classed by the British Corporation, with record of docking survey 6.49 without special condition, and notation of Annual Survey 6.49 assigned.

BS\*


6.49 Mch. ✓ Without.

Annual Survey 6.49.

ENDORSEMENT OF CLASS (Group B).

Shell plates B.7 &amp; C.7 etc. (p &amp; s) indented.

Ann L.L. survey also held  
(per Fbd.)



© 2021

Lloyd's Register Foundation