

Abeking & Rasmussen Ltd No 5892/4

Cert orig. F

COPY FOR 5894 when received.

Page — 2 — of Ltr from Bremen Sur dated

2.8.63

With regard to item No.7 it would appear the Builders ordered two oil anchor lights as they have certificates covering two - also the lights for the sister ship have been examined and there are two oil anchor lights but no N.U.C. lights, but there are red slides, however, most of the Shipyard personnel are on holiday just now so this particular item will be discussed and we will communicate with you again.

An amended Rpt.10 will be prepared and forwarded to you in due course.

Yours faithfully,  
The Surveyors,

Per: - *[Signature]*

The Secretary  
LONDON

P.S. We would add that as our First Entry Report is held up by holidays. We have advised the Chittagong Surveyors of the necessary examination of the ferry on arrival at Chaina and requested he arranges the cut off chocks before she proceeds to Dacca.

(Copy with  
Yard 5892 "INTA Dacca")



© 2021

Lloyd's Register  
Foundation

011544-011554-0067