

"EARNER"

Rpt. Hul. No. 52200.

Before this case can receive consideration the Rpt 8 should be returned to the Hull Surveyors and they should be requested to insert in the appropriate space their recommendation respecting the permanent repairs to the damaged forecastle side plate.

J.C.D.
6/11/45
16.11.45.



© 2021

Lloyd's Register
Foundation

011555-011569-0121