

COPY

Ship's name

Prosper.

Port

d Kg

No.

186L2

Class is subject to

me

Last survey date

26.6.65

Sp S due 5.65 pp to 5.65 app provided G. L. & held.

General Examⁿ now held

MBS due 6.65 now held

ME L Cylinder cover found cracked and temporary repairs effected by fitting a steel double plate and a cement box. It is recommended that Cylinder cover be renewed by 5.65

It is submitted that this vessel is eligible to remain as CLASSED.

MBS 6.65 now subject as recommended. A further

submitted test/assessment of Sp S. needs approval



©2021

Lloyd's Register
Foundation