

POSTPONED SURVEYS.

Case of the..... T.W.Sc. s.s. "TETI"

No. 79155..... in Reg. Bk..... tons, Built.....

Classed..... Owners.....

Port of Registry.....

Survey Due..... Repairs to indented and wavy shell plating etc. and indented keel and bottom plating etc. by 10.52.
75 fathoms of worn chain cable to be renewed and 15 fms. supplied as soon as possible by 11.52. (38 fms. 75 fms. needed for repairs)
Both propellers to be renewed and both screwshafts examined by 10.52.

In reply to enquiry the Owners have informed the Piraeus Surveyors that this vessel is laid up at that port and request that the renewal of the chain cable be deferred until February next when 4 new Diesel engines will be fitted.

No mention is made with regard to the other outstanding items of survey and it is concluded that these will also be dealt with in February next.

Committee's Minute.....

FRI. 31 OCT '952

Decision.....

Deferred

*must be done in
next 2 months
before 2.10.1952*



© 2021

Lloyd's Register
Foundation

011595-011602-0003