

29th August, 1952.

One

is

PIRAHUS

"TATI" 6033. As recommended, except that the assignment of the Special Survey notation on the hull has been deferred pending the effecting of the repairs recommended by you and 75 fathoms of worn chain cable being renewed and 15 fathoms supplied as soon as possible. In this connection I have to inform you that this vessel was originally supplied with and still requires 210 fathoms of $1\frac{3}{8}$ " diameter W.I. chain cable and the Committee consider that this vessel's equipment must be brought up to Rule requirements before the end of November next if the vessel is to retain her classification with this Society.



© 2021

Lloyd's Register
Foundation

011595-011602-0028