

C O P Y

I N S P E C T I O N R E P O R T
=====

SS.

~~M.V.~~ "MONT SANDRA".
=====

An inspection of the Kidde fire extinguishing equipment was carried out on board the above vessel and all cylinders were disconnected and weighed and found to be fully charged, as per the enclosed sheet.

The two gang release units were examined and the pistons operated by hand quite satisfactorily.

The pull box, together with the main distribution valve, were examined and tested for free operation and found to be in good working order.

All piping, where accessible, was thoroughly examined and it was found that the piping in the Bilge was in need of being thoroughly cleaned and blown out, which was reported at the time of the inspection.

In conclusion all the cylinders were reinstalled and the installation left in commission ready for immediate operation.

(Sgd.) L.L. REED COOPER

Inspection Department.

I.487/LRC/VS
20.2.53.



© 2021

Lloyd's Register
Foundation

011595-011502-0157