

COPY

Ship's name

LEONIDAS

Port

Batona (93)

No.

5008

Class is subject to

None.

Last survey date

14/12/63.

Repair.

One blade of propeller found broken off (shear submerged propeller) & opposite blade not cracked; the

Surveyor recommends that the propeller be renewed
by 5/64 (GWS limit).

NOTED.

as noted, subject would recommend.

3/12/64



© 2021

Lloyd's Register
Foundation

011595-011602-0187