

011628-011635-0293

5 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

26 JAN 1950

S NAME

EASTERN.

REPORT

H.Kg.

No. 9729.

As of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE-&-WEAR AND TEAR.

The lower part of the thrust block was found to be cracked and a new casting of heavier section has now been made and fitted.

Alterations: A refrigerating installation has now been fitted in accordance with approved plans.

It is submitted the vessel is eligible to remain as classed with out record of Survey as recommended.

Extract for RMC. (with plan).



© 2021

Lloyd's Register
Foundation