

Received by Chief Ship Surveyor

GB

Received from Chief Ship Surveyor

31 MAR 1949

NAME

"S W A R O Z Y C"

REPORT

Gdy.

No. 2183

arks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

orsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)


he GDYNIA Surveyors report this tug placed on floating dock, coated, and repairs effected to cracked deck stringer plates (p & s).

IF IS SUBMITTED the vessel is eligible to remain as classed, with record of docking survey 12.49.

Gdansk. ✓

C.S.S. Records Dept.

to note, Cracked deck plating.



AR



© 2021

Lloyd's Register  
Foundation

011636-011645-2017