

1

Messrs. Yarrow & Co. Ltd., Glasgow.

Yard No. 2104.

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

GB Quarter Wheel
SHIP'S NAME m.s. "PONDAUNG" REPORT Gls. No. 85051

For the CHIEF SHIP SURVEYOR ~~AND CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey FIRST ENTRY ~~When Arrives~~

L. 130'-0" B. 34'-0" D. 5'-6"

This Quarter Wheel Motor Ship has been built at Glasgow for service in Burma and is being towed to Rangoon.

The scantlings and arrangements, as reported, conform with the Society's Revised Rules and Regulations, and are in accordance with or equivalent to those shown on the approved plans.

IT IS THEREFORE SUBMITTED the ship is eligible to be classed:-

MA1 "For Service on the River Irrawaddy, Burma (limiting port seawards, Rangoon)"

WHEN a report, of the satisfactory condition of the ship on arrival at its destination port, of the laying of wood ceiling in the hold spaces and of the completion of fitting out for service, has been received.

1 dk; pt E.W; N.S.
6BH, LACP.
O.L. 149'-6"
Extreme breadth: 35'-3"
Rise of floor: Nil.

The Certificate of Classification to be endorsed "Cargo Battens not fitted" and the same notation to be printed in the Register Book.

(e) 7/8"

See before dated 4/5/56

C.S.S. Records Dept.
to note Shell and deck plating galvanised.

The GLASGOW Surveyors should be advised it is concluded the service limits "For Service on River Irrawaddy - Burma limiting port seawards Rangoon" and equipment of anchors and cables has been approved and meets with Owners' approval and requirements. (Refer Secretary's letters dated 30.1.56 & 5.9.55.)

IT IS FURTHER SUBMITTED the RANGOON Surveyor be requested to carry out a General Examination of the ship in dry dock on its arrival there and ~~to furnish a Report~~ when the ceiling in the hold spaces has been laid and fitting out for service completed, furnish a Rpt 8 on the case.

2/5
2/5

R.S.D.
2.5.56.



© 2021

Lloyd's Register Foundation

011636-011645-0296