

Further copy has been sent to the Oslo Surveyors.

COPY.

Lloyd's Register of Shipping,

united with THE BRITISH CORPORATION REGISTER.

Port of ROTTERDAM.

JWL.

18th June, 1957.

BELONGS TO

ROTTERDAM REPORT No.

43604 B

This is to Certify that I have

Donkey Part & Tailshaft

Surveyed the Boiler and Machinery of the m.s. "MAX MANUS", 5029 tons

gross of Oslo, whilst lying afloat and placed on pontoon at this port on the

3rd April, 1957 and subsequently for Condition, Tailshaft Survey, Continuous Survey of Engines and Donkey Boiler Survey

and that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report stating that all

recommendations made by me in connection therewith have

been carried out to my satisfaction, and that I have

Recommended that the record of Donkey Boiler Survey 4-57,

Tailshaft Survey seen 4-57 Continuous Liner and of Continuous Survey of engines (with date)

be made in the Register Book in the case of this vessel when

the survey has been completed.

Parts now examined:—

Main engine: Chaindrive for camshafts.

Side and centre Nos. 1, 2 and 3 connecting rods, top ends & guides,

Lever of M.E. driven scavenging pump.

M.E. driven pumps.

Crankcase doors & explosion relief devices.

Feedpumps (p.a.), oil burning fuel pumps (p.a.), transfer pump (p.f.)

Piping arrangements.

Fresh water cooler, lubricating oil cooler.

Inboard independent air compressor.

Both main air receivers.

Daily service tanks.

Evaporator.

Steering machinery, windlass and fire extinguishing arrangements.

Electrical Equipment.

Donkey boilers.

Tailshaft.

Propeller, sea connections and outside fastenings.


Engineer Surveyor to Lloyd's Register.

JOB.F. VROUWES.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or Surveyors, or other Officers or Agents of the Society."

C.S.)



© 2021

011646-011656-0211

Lloyd's Register
Foundation