


"SOUTHERN ENTERPRISE"

MBA 2132.

Before this case receives consideration, the Surveyor should be requested to state his reasons for making the class subject to the Main Engine lubricating oil pump drive gears being renewed by July, 1963 and in future similar cases when a subject of class is imposed the reasons should be clearly stated on the Report.

JW



16.10.62.

© 2021

Lloyd's Register
Foundation

011646-011656-0284