

Rpt. 8

REPORT OF SHIP SURVEYS AND REPAIRS

Received London

-4 OCT. 1962

Ship's Name ~~SS~~/MS SOUTHERN ENTERPRISE

239 Gross tons of Port Victoria Seychelles.

Is there a rpt. 9? Yes

Port Mombasa.

Rpt. No. 2132

No. of visits 7

First date 24/9/62

Last date 28/9/62

Interim Cert. issued & copy herewith? Yes

Damage rpt. issued & copy herewith? -

Last rpt. (H.Q. only) -

1970 MSA

Date of completing rpt. 29/9/62

Surveyed at, if different from Port above -

Surveyed afloat and/or in D.D. Both

Last date of examination in D.D. 27/9/62

Has a Load Line Survey been held? No

Freeboard Marks verified Yes

State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig)

Survey fees DS & Repairs.

Damage fee -

Expenses

£.25.0.0

12/-

S.A. fee

I have surveyed the above ship in accordance with the Rules for Docking Survey.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

The ship placed on the slipway shellplating, stemframe, and rudder, superstructures, decks, casings, hatchways, ventilators and air pipes and closing appliances, mast and rigging, anchors (2B & 1S) and cables ranged 135x3/4". All cargo tanks and cofferdam.

Repairs effected.

Rudder lifted and gudgeon bushes renewed (worn). Wood bearing on rudder stock renewed. Steering wheel chain drum and bevel drive overhauled, slack keys renewed and bearings adjusted.

0.1 cargo tank/fwd cofferdam bulkhead.

Bulkhead holed at base, port and starboard. Welded doublers p.t.o

I recommend that this ship remain as classed with/without fresh record of dry docking 9.62

These conditions of class are recommended to be retained, imposed, amended or deleted, particulars to be stated above and on the interim certificate.)

Name of Committee

WEDNESDAY 31 OCT 1962

Signature

DS. 9.62 Subject (m)

Surveyor to Lloyd's Register of Shipping

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT



© 2021

Lloyd's Register Foundation

01646-01656-0285

D

18 OCT 1962

should be repairs, rejected to d.

fitted. Cofferdam filled and tested on completion and found tight.

0.0.2.3

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC. The reason for repairs must be stated and repairs on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs and, besides being detailed above, should be noted in the following summary. *State what action has been taken regarding items which are subjects of class or in SRL Appendix, whether outstanding or new.* Any alterations in existing particulars in the Register Book should also be reported above.

SUMMARY OF DAMAGE REPAIRS	SHELL PLATES	FRAMES	DECK PLATES	BEAMS	OTHER ITEMS
Renewed					
Removed and faired or replaced					
Faired or repaired in place					

Rpt.
Is th
Interi
& co
co

1
2 V
Con.
&
3
4 b
5
6 p
8
10 s
11 p
13
16 C
bla
17
18
CS, w
lubri

(Where
be retain
must be
Date of
Minute

circumstances and account thereof or recommendations described fully under "defects and repairs".
until the due date of the next Periodical Examination. Where repairs have been effected or it is
be counted from forward.