

21 DEC 1964

Ship's name SAND SKIFFER Port a) SOU No. 29208  
b) SOU No. 29232  
 Last survey date 24.10.64.  
 Class is subject to

indented shell plate C.5 (p.s) and indented No.1 fore-castle sheerstrake plate and deck plating in way (p.s) also to shell plates A.2, B.1, D.3 & 4 (s.s.a) being specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix (as before ~~xxxxxx~~)

Surveys due SPECIAL SURVEY (C) due 11,64. Postponement until 11,65 approved 18.11.64 provided G.E. is held afloat at an early date.

Nature of present survey (afloat and in drydock)

- a) Docking: W & T Repairs: Examination of S.R.L. & App.items.  
 b) Equipment: bower anchor and 1 length of chain cable supplied to replace lost equipment.

Is interim certificate in order Yes/No/None

Items outstanding if any for SS

SS proposed to be completed by

Recommendation SUBMITTED record of DS 6,64 be assigned, subject as above.

DS 6,64 Subject

IN S.R.L. APPENDIX

Shell plates A.3 & 5, B.12 (p.s),  
 A.11, B.11, C.6 (s.s) slightly indented.

ENGRS. TO NOTE ~~RT~~ 29208

C.S. to note.



© 2021 ✓

P.T.O.

Lloyd's Register  
 Foundation

IT IS FURTHER SUBMITTED the Surveyors  
be advised it is concluded the steering gear  
chains have been renewed of tested material, but  
confirmation is desired.

*u22/12*

*See letter  
22.1-65*

*ff  
2-12-64*

S.R.L. Appendix (as before)  
Surveys due  
nature of present survey (effort and in drydock)  
a) Docking & T. Repairs: Examination of S.R.L. & App. Items.  
b) Equipment: Power anchor and 1 length of main cable  
supplied to replace lost equipment.  
Is interim certificate in order  
Items outstanding if any for SS  
Yes/No/None

SS proposed to be completed by

Recommendation  
Detailed record of DS 6,64 be assigned  
subject as above.

DS 6,64 subject  
IN S.R.L. APPENDIX  
Small plates A.3, 5, B.12 (p.a.)  
A.11, B.11, 12 (p.a.) slightly damaged.

F.T.O.



© 2021

Lloyd's Register  
Foundation