

COPY

Ship's name "SAND SKIPPER" Port a) SOU No. 29208
 b) SOU 29232
Last survey date 24.10.64.

Class is subject to

indented shell plate C.5 (p.s) and indented No.1 forecastle sheerstrake plate and deck plating in way (p.s) also to shell plates A.2, B.1, D.3 & 4 (s.s.a) being specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix (as before or none)

Surveys due

SPECIAL SURVEY (C) due 11.64. Postponement until 11.65 approved 18.11.64 provided G.E. is held afloat at an early date.

Nature of present survey (afloat and in drydock)

- a) Docking: W & T Repairs: Examination of S.R.L. & App. items.
- b) Equipment:.. bower anchor and 1 length of chain cable supplied to replace lost equipment.

Is interim certificate in order

Yes/No/None

Items outstanding if any for SS

SS proposed to be completed by

Recommendation

SUBMITTED record of DS 6,64 be assigned, subject as above.

DS 6,64 Subject

IN S.R.L. APPENDIX

Shell plates A.3 & 5, B.12 (p.s),
A.11, B.11, C.6 (s.s) slightly indented.

ENGRS. TO NOTE 29208

C.S.S. Records
to note.



© 2021

Lloyd's Register
Foundation

IT IS FURTHER SUBMITTED the Surveyors
be advised it is concluded the steering gear ~~air~~
chains have been renewed of tested material, but
confirmation is desired.

*see letter
22/1/65*

*J.S.
2-12-64*



© 2021

Lloyd's Register
Foundation