

6 SEP 1953

"PORJUS"

IT IS SUBMITTED before this case receives the consideration of the Committee, the Surveyors be informed ~~that:~~ *it is concluded*

- 1) They are in error in reporting 3 <sup>bow</sup> bower anchors and a stream anchor, <sup>ON BOARD</sup> as when this ship was classed the anchor equipment consisted of 2 bower anchors and a stream anchor.
  - 2) The port bower anchor has been retained in the hawsepipe.
  - 3) The strums were removed for examination of the plating in way, and
  - 4) The damaged port bower anchor will prove efficient if required for use in an emergency,
- but confirmation is desired.
- Se. after*
- BM.*  
*9.9.53.*
- 4*



© 2021

Lloyd's Register  
Foundation

011657-011664-0069