

19th October, 1954.

EMBURG

8, 76, 81 - As recommended.

C. 20983, 92, 93 As recommended.

9 "C.J. HAMBRO" As recommended. I shall, however, be glad if will kindly designate No. 2 (intermediate) generator by its position, and if possible forward a rough sketch showing all generators in the ship.

5 "PORJUS" As recommended except that the Screwshaft record has withheld pending the renewal of this shaft, I shall be glad to give your confirmation that damage now reported to the bottom side shell plating is situated on the Port and Starboard sides, this information has been omitted from your report.

"LERO" Before your report No. 20982 receives the consideration the Committee I shall be glad if you would furnish a sketch illustrating the alterations now effected to the hatchway coverings of deep tanks.