

Port KODAK

11th November, 1964.

and that all ~~my~~ ^{our} recommendations have been carried out to ~~my~~ ^{our} satisfaction. I We
are ~~in~~ reporting accordingly and recommending to the Committee of Lloyd's Register
of Shipping that the machinery classification should be retained and the following
survey records assigned ES (with date) on completion of survey and TSN(CL)
10,64 subject to any outstanding condition of class being dealt with as
previously recommended.

FOR U.S.

Butterworth heater.

Kate Munn J. J. J. J. J.
Surveyor to Lloyd's Register of Shipping

TS	Tailshaft Survey
TS(CL)	Tailshaft Survey—Continuous Liner
TSN	Tailshaft renewed
TS(OG)	Tailshaft Survey—Oil Gland

JH:sk

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

FOR LONDON