

ring Chains (Size and Test)

None

Windlass

Electric

Beats 2 Wo

(includ

ing in Hclds. thickness and material 65 S.W. on 38 Bearers

Cargo Battens, thickness, material and spacing

(Req. 1a.)

(Received at London Office) 20-10-53 19 53

No. 580 Place Ku. Date 22nd Sept., 19 53

We request that the Committee of Lloyd's Register will instruct the Society's Surveyors to Specially Survey during Construction the Hull, Engines and Boilers of the Vessel No. 580 building by Messrs. Mitsui Shipbuilding & Engineering Co., Ltd., Tamano Works for Messrs. Mitsui Steamship Co., Ltd.

of 6,900 G/Tons. Length 142.00M, Breadth 19.30M, Depth 12.40M intended to be Classed +100A1, +LMC(C.S.) and +R.M.C.

We undertake to arrange for every facility to be given to the Surveyors to carry out the duty in question, and we agree to pay the fees for the Surveyors' services, in addition to the actual travelling and other expenses incurred by the Surveyors in connection therewith.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of shipping, which provide that:-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.

Engine Makers Mitsui Shipbuilding & Engineering Co., Ltd., Tamano Works

Boiler Makers do.

Signature

To the Secretary, S. Tanaka, Senior Managing Director  
Lloyd's Register of Shipping,  
71, Fenchurch Street, London, E.C.3.

NOTE.—To avoid misunderstanding, orders for materials requiring to be tested should be marked as follows:—  
"Inspection and Testing by Lloyd's Register Surveyors to the Society's requirements."

IC-6, 51 Kobe.

011671-011677-0194

Lloyd's Register Foundation

(Special notations, where part of class, to be sta

amount of Entry Fee £ 21,50,000 fees applied for,

Cargo Service 15,000 MAY 27, 1954 19

Special Survey Fee £ :