

LLOYD'S REGISTER OF SHIPPING

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name S.S. "JANUDA"

Official No. 182885

Port of Registry BOMBAY

This ship has been under survey at Bombay for Annual Load Line Survey

on 14th, 23rd and 25th August 1963 ~~1961~~ and the following alterations to the conditions of assignment of loadlines have now been ~~affected~~ found:—

No. 4 hatchway on Freeboard Deck (tween deck) now fitted with wooden covers (5 feet long x $2\frac{1}{2}$ " thick) with metal bands on ends and not steel covers as stated on original C11.

All hatchways on Upper Deck (shelter deck) were found fitted with wooden covers (5 feet long x $2\frac{1}{2}$ " thick) with metal bands on ends and not steel covers as stated on original C11.

Shah
SURVEYOR TO LLOYD'S REGISTER.

haver
Did
11.9.63

A copy of this Report has been placed on board.

