

8th June, 1960.

PIRAEUS

8432, 35 - As recommended.

8412 "SNJEZNIK" The contents of this report have been noted.

8441 "MAGROLIA" - As recommended. You should state the reason why the tailshaft was changed, and should further state if the shaft now fitted has been previously used.

Lloyd's Register  
Foundation

011712-011717-0143