

12 MAR 1964

EA
Ship's name "BEECH HILL"

Port

HFX. No. 8380

Last survey date 7.1.64.

Class is subject to

set in shell plates Nos.3 in 2nd and 3rd strakes below sheer (s.s.f), indented shell plates F.6, G.4 & 5, H.5 etc. (p.s.f) and inner bottom plating in No.5 hold, also to forward bulkhead of No.5 hold (s.s)(holed) also indented shell plates G.8 and H.9 (p.s) being specially examined and dealt with as necessary by the Special Survey.

S.R.L. Appendix (as before ~~XXXXXX~~)

Surveys due

SPECIAL SURVEY (C) due 5.63. Postponement until 5.64 approved 21.11.63. G.E. held Pir.9.63.

Nature of present survey (afloat ~~XXXXXXXXXXXXXXXXXX~~)

Equipment: Damaged bower anchor removed.

Is interim certificate in order

Yes/No/None

Items outstanding if any for SS

ALL ITEMS.

SS proposed to be completed by

Recommendation SUBMITTED ACTION be DEFERRED for Special Survey by 5.64, subject as above and to a bower anchor being supplied at the earliest opportunity.

SUBJECT.

IN S.R.L. APPENDIX.

Top of starboard hawse pipe E.W.

OFFICE NOTE.

Bottom stiffened in Nos.2,3,4,5 & 6
D.B. tanks - Hul.4,50.

SPK.
5/3/64



© 2021

Lloyd's Register
Foundation