

21 FEB 1957

The clearance between the propeller and the Skanframe is to be the responsibility of the Builders and owners.

Castings and forgings to be of
 weldable quality containing not
 more than 0.23% carbon.

SHIP No 70-71.


011757-011765-0054


© 2020




Lloyd's Register Foundation

RECORDS DEPT.
LONDON.



~ JOSEPH 

Stemprane



© 2020

011 757-011765
Lloyd's Register
Foundation