

COPY

LLOYD'S REGISTER OF SHIPPING



Port of Vancouver, B.C.

27th May, 1959.

This is to Certify that ^{we} ~~I~~ have

^{Donkey} ~~Surveyed the~~ ^{Part} ~~Boiler~~ and ~~Machinery~~ of the M.V. "PACIFIC WIND"
ex "UNITANKER" 1561 tons gross of Vancouver as she lay afloat
and on floating dock at Vancouver and Victoria, B.C. on the 20th
April, 1959 and subsequently for Advancement of Reclassification
Survey ^{we} ~~I~~ have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all
recommendations made by ^{us} ~~me~~ in connection therewith have
been carried out to ^{our} ~~my~~ satisfaction, and that ^{we} ~~I~~ have
Recommended that the record of CS (with date) DBS 5, 59
and TS 5, 59

be made in the Register Book in the case of this vessel when
the survey has been completed.

Parts now examined :-

STARBOARD MAIN ENGINE:-

Nos. 1, 3, 4 & 7 cylinder covers, pistons, rods, crankpin and bearings,
valves and valve gear.
All main bearings and scavenge pump complete.
Port and Starboard Main Engine Drive Lubricating Oil Pump.
Tailshaft, propeller, fastenings and sea connection.
Intermediate shafts and bearings.
Port main engine P.W. Circ. Pump and Lub. oil cooler.
Port bilge pump and O.F. Transfer Pump and L.O. Sump Pump.
The Starboard 75 KW Auxiliary Engine.
The 3 main and 1 auxiliary air receivers.
Steering engine.
Pumping arrangements.

J.A. Stewart and T. Taylor
J.A. STEWART and T. TAYLOR

Engineer Surveyor to Lloyd's Register

rtificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be
understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any
error in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society,
or error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents
of the Society."

1. (C.S.) 50m.6.56.

(MADE AND PRINTED IN ENGLAND.)

011757-01965

Lloyd's Register
Foundation